



Rangeland Auto Repair Corp
 4609 East Service Road
 Hiway 12
 P.O. Box 67
 Coronation, AB T0C 1C0
 403-578-2250
 2014rangelandauto@gmail.com

Date	Invoice #
2021-06-30	10878

George Nichols
 Box 997
 Castor, AB
 T0C 0X0

P.O. No.	Terms

Qty	Description	Rate	Amount
3.5	Service call to check out A/C, both switches by dryer shorting out causing clutch not enough VS to kick in, need to order parts, Replaced both switches, vacuumed system held vacuum, charged A/C and confirmed proper operation	110.00	385.00
1	51578982 Filter Dryer w/switch	161.56	161.56
1	A65779 Switch	201.83	201.83
3	R134A Freon per Lb	15.38	46.14
1	Miscellaneous shop supplies	16.68	16.68
1	Freight	20.00	20.00
	Case 3394		
			\$831.21

Retorque Tires AFTER 50
 KM

GST@5.0%
 Total Tax

Sales Tax Summary

41.56
 41.56

Total

\$872.77

GST/HST No. 834910192

*Master Card.
 Aug 9/21*