



Willerton Ski-Doo & Golf Cart LTD
 1802-14h Ave
 Wainwright, AB T9W1L2
 1-780-842-4775

Repair Order

In Date: Jul. 21,2022

P/U Date: Aug. 08,2022

Service Writer: JCopeland

RO #24164



Sold To :	Unit Information						
Bennefeld, Dwayne Box 100 Hardisty, AB T0B1V0 (P) 780-888-2565	Year	Manufacturer	Model	VIN/HIN/SN	Engine #	Keyboard	Miles/Hours
	2008	Kawasaki	KVF 360	JKBVFHA188B575561	KVF360AF		1017.04

Job: Full Service ATV

Kawasaki KVF 360 2008 - JKBVFHA188B575561

Full service/ check over on atv
 Back brakes are seized
 May need some new tires

Part #	Part Description	Qty	Price	Unit Extension	Extension
DPR8EA-9	NGK DPR8EA-9 Spark Plug	1	\$4.99	\$4.99	\$4.99
218102	HOOK STLH REPLACEMENT BK	1	\$18.99	\$18.99	\$18.99
1358	Oil Filter	1	\$24.99	\$24.99	\$24.99
779141	OIL 4T 0W40 SYNTHETIC 1 Litre per 5 GAL/18,92L	2.5	\$18.99	\$18.99	\$47.48

Parts Subtotal: \$96.45

Technician	Description	Hours	Rate	Discount	Labor Cost
HMackey	Full Service ATV	6.50	\$120.00	0.00 %	\$780.00

Labor Subtotal: \$780.00

Fees	Qty	Fee Cost
Shop Supplies	1	\$25.00

Fees Subtotal: \$25.00

Tax: \$45.07

Job Subtotal: \$946.52

Resolution:

Change engine oil and filter
 Check all switches work & cables lubricated.
 4x4 switch wasn't working, removed rear fenders and fuel tank to diagnose. Checked switch and actuator both tested good. Reset belt switch and 4x4 is working good now.
 Quad would start then run intermittently. Found a connection in the wiring that someone had added a linkage wire between 2 grounds. Making intermittent connection. Removed connection and hooked grounds to proper placement.
 Clean air box and filter
 Change spark plug
 Check Valve Cover Gasket
 Check battery charge
 Check drive belt. Good
 Clean clutch, check over internal components
 Check CVT Boots
 Grease all areas
 Check brake lines, calipers, fluid, pads.
 Changed fluid in front brakes
 Check over cooling system (coolant). Air cooled
 Check exhaust

Recommended Repairs:

N/A